

Caspian Airlines
Str. Next Police Station 150
Golha BLVD – Karaj Special Road
Tehran, Iran

ASD Aviation Spares Distribution GmbH
Robert-Bunsen-Strasse 73 A
65428 Ruesselsheim
Germany
Tel: (49) 06142-40918-32
Fax: (49) 06142-40918-11
Email: kuehn@asd-air.com

COST ESTIMATE No. A4033396

Customer Order – No.

Date

WO-50455

October 16, 2018

Item	Qty.	P/N	Description	Workscope	Total Price €
1	1ea	696233B S/N: 4167	Constant Speed Drive	Repair	

ESTIMATE TOTAL:

3.137,00 €

Findings:

Performed incoming inspection. Found Filters contaminated with Metal. Opened and inspected Unit. Found internal contamination. Unit requires cleaning and flush of Housing.

Following Parts are required: Packings, Filters

*****WARRANTY DENIED, DUE TO CONTAMINATION*****

Terms and conditions:

Teardown and Inspections fee:

EUR 1.500,00 (will be charged if the CE is denied)

Point of delivery:

ex works Ruesselsheim

Payment terms:

C.O.D

Validity of cost estimate:

30 days.

Quote is subject to change until final test

Please advise your disposition instructions:

Accepted: _____ Rejected: _____ Date: _____